

POWER CORE E90 SPRINT CHARGER PORT REPLACEMENT PROCEDURES

PART #W13111401106

Required Tools: (Not included)


- A. Phillips screwdriver
- B. Flat screwdriver
- C. Long needle pliers

WARNING

CAUTION: To avoid potential shock or other injury, turn power switch <u>OFF</u> and disconnect charger before conducting any assembly or maintenance procedures. Failure to follow these steps in the correct order may cause irreparable damage.


Step 1

Using a Phillips screwdriver, remove the five (5) screws from the side with the power switch.




Step 2

Pull the cover off. Be careful not to damage the wires for the charger port and power switch. Set cover aside.




Step 3

Locate and disconnect the charger port from the controller.




Step 4

Disconnect the black wire from the power switch.




Step 5

Using a flat screwdriver, remove the glue at the back of the charger port.



Step 6

Using long needle pliers, remove the lock nut at the back of the charger port and push it out of the battery cover.



Step 7

Reverse the procedures

ATTENTION: Charge battery 12 hours before using.