

POWER CORE E90 SPRINT FOOT PLATFORMS REPLACEMENT PROCEDURES

PART # W13112163017/W13112144017

Required Tools: (Not included)

- A. 6 mm Allen wrench
- B. Phillips screwdriver

I WARNING

CAUTION: To avoid potential shock or other injury, turn power switch <u>OFF</u> and disconnect charger before conducting any assembly or maintenance procedures. Failure to follow these steps in the correct order may cause irreparable damage.

Step 1

Using a size 6 mm Allen wrench, remove four (4) bolts from under the foot platform (two (2) on each side). Slide the platform bracket down.



Step 2

If replacing only the plastic platform, use a Phillips screwdriver to remove four (4) screws on top of the platform (two (2) on each side). Lift the plastic off from the bracket.



Reverse the steps.

ATTENTION: Charge battery 12 hours before using.