

# **POWER CORE E90 SPRINT CONTROLLER REPLACEMENT PROCEDURES**

PART # W13112144015

#### **Required Tools: (Not included)**

A. Phillips screwdriver

## WARNING

**A** CAUTION: To avoid potential shock or other injury, turn power switch <u>OFF</u> and disconnect charger before conducting any assembly or maintenance procedures. Failure to follow these steps in the correct order may cause irreparable damage.

#### Step 1

Using a Phillips screwdriver, remove the five (5) screws from the side with the power switch.




#### Step 2

Pull the cover off. Be careful not to damage the wires for the charger port and power switch. Set cover aside.



#### Step 3

Using a Phillips screwdriver, remove the two (2) screws that hold the controller onto the frame.



# Step 7

Reverse the procedures

ATTENTION: Charge battery 12 hours before using.

## Step 4

Disconnect all connectors from the controller and remove the controller.

