

**Required Tools: (Not included)**

A. Two (2) 5 mm Allen wrenches

**⚠ WARNING**

**⚠ CAUTION:** To avoid potential shock or other injury, turn power switch OFF and disconnect charger before conducting any assembly or maintenance procedures. Failure to follow these steps in the correct order may cause irreparable damage.

**Step 1**

Using two (2) 5 mm Allen wrenches, loosen the axle bolt from the fork. Slide the wheel down.

**Step 2**

Reverse the steps.

**ATTENTION: Charge battery 10 hours before using.**